


Part-1

Performa for the Safety School Building
(To be filled by the Head of School/ Institute)

1. Name of School : SACRED HEART CONVENT SCHOOL
2. Location : SARABHA NAGAR, LUDHIANA
3. Plot Area : G.F. F.F. S.F. T.F. = Total
4. Plinth Area : 69870 - 44492 - 34885 - 14124 = 16337
5. Number of Storey : G + 4 (1633)
6. Year of Construction of Building : 2005
7. Supervision of the qualified Engineer,
The following details may be given :
 - a) Name of the Engineer : R. D. P. SHARMA
 - b) Address : 25, ATAM NAGAR, LDH
 - c) Set of Structure Drawing used in the
Construction if available : ATTACHED
 - d) Name of the Architect : VIKAS SHARMA
8. Whether the building has been constructed for the purpose of :
 - a) School (Yes/ No) YES
 - b) Residential purpose and converted
for use as a school (Yes/ No) NO
9. Materials used for Roof :
 - a) R.C.C Slabs (Yes/ No) YES
 - b) R.S. Joists and Battens (Yes/ No) NO
 - c) Wooden Joists and Battens (Yes/ No) NO
10. Materials used for walls :
 - a) Mud Mortar (Yes/ No) NO
 - b) Cement Mortar (Yes/ No) YES
 - c) Plaster (i) Lime Mortar (Yes/ No) NO
(ii) Cement Mortar (Yes/ No) YES
11. Flooring:
 - a) Conglomerate (Verified Tiles) (Yes/ No) YES
 - b) Terrazzo (Yes/ No) NO
 - c) Brick Paving (Yes/ No) NO
12. Detailed Drawing indicating dimensions
of the rooms along with size and location
of doors and windows : ATTACHED


Signature with stamp of
The Head of the School/ Institute
Principal
Sacred Heart Convent
Senior Secondary School
Sarabha Nagar, Ludhiana

21/2023-24/ 54

dt 3/5/2023

PART-II

(To be filled by the S.D.E.)

a) I have visited the above mentioned school on dated 02/5/2023 and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.

b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.

c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.

d) This building can be safety occupied for normal use upto
(indicate upto which it can be used)

Amrinder
Sub Divisional Engineer

Sub Divisional Engineer,
Provincial Sub Division No. 3,
P.W.D. B&R, Br. LUDHIANA.

m
02/5/2023